


TAMAN BIDOR NUSAWAJA



2091 SQFT
4 ROOMS + 4 BATHROOMS
DOUBLE STOREY TERRACE HOUSE



DOUBLE STOREY TERRACE HOUSE

91 UNITS

DOUBLE STOREY TERRACE SHOPLOT

15 UNITS





Tapah Road Railway Station
17km



Sultan Azlan Shah Airport
60km

Ipooh 63km
Selangor 90km
Kuala Lumpur 140km



SMK Bidor
4km




SK Bidor 2
3.3km

TAMAN SRI MAS



SMK Choong Hua
4km



SJK (C) Choong Hua
5km

SANITARY FITTINGS

Water closet (WC) | 4 units
Handwash basin | 4 units
Shower head | 4 units
Basin tap | 4 units
Water tap | 5 units
Kitchen sink | 1 unit

ELECTRICAL FITTINGS

DB box | 4 units
Lighting point | 15 units
Aircond (AC) point | 2 units
Ceiling fan point | 2 units
Plug point | 8 units
TV point | 1 unit
Water heater point | 1 unit

BUILDING SPECS



Structure | Reinforced concrete (RC)
Wall | Brick wall
Roof | Concrete roof tiling
Ceiling | Plaster/ skim/ cement board
Window | Glass window with aluminium frame
Door | Timber door

FLOOR FINISHES

Car porch | Stamped concrete
Living | Ceramic tiles
Dining | Ceramic tiles
Kitchen | Ceramic tiles
All toilets | Ceramic tiles
All bedrooms | Ceramic tiles
Staircase | Ceramic tiles

WALL FINISHES

Exterior | Weather-resistant paint
Interior | Ceramic tiles
Kitchen | 1500mm height wall tiles
All toilets | Ceiling height wall tiles



Masjid Abu Hurairah
2km



Batang Padang
Golf Course
2.5km



Transport (Railway)



Transport (Airport)



Transport (Bus)



Education (School)



Mosque



Sport Centre (Golf)



Bidor Bus Terminal
5km



Stesen KTMB Sungkai
18km

**TAMAN
BIDOR
NUSAWAJA**



A project by ECO MAJU HOLDING SDN BHD

Visit us :

W-3-05, The Gamuda Suites.12, Jalan Anggerik Vanilla 31/99, sek 31, Kota Kemuning, 40460 Shah Alam, Selangor

Contact us :

+012 2839 919

www.ecomaju.com.my

All renderings & illustrations in this brochure are the artist's impressions. The information contained herein is subject to change without notification as may be required by the authorities or developer's architect. Whilst every care has been taken in providing these information, the owner developers & managers cannot be held responsible for variations.